

List of outstanding jobs needed for the tracker.

(Or at least the ones I know of, some may already have been done)

1. The new bubblers and oxygen sensors need to be built onto a panel and plumbed in
2. The Helium exhaust from the bubblers needs to be ducted from the hall
3. New side protection plate need to be made and fitted to the cryo's as existing ones do not fit well.
4. The helium lines on cryo's 1, 2 and 3 need to be secured in a robust way as cryo 4
5. The yellow lighting needs to be found and checked for the replacement of the diffuser
6. Once the diffuser is replaced leak tests should be carried out and any problems dealt with
7. Vacuum pump stands need to be fitted and secured
8. I believe that the Didcot store is being tidied to allow room for the RF equipment, someone needs to ensure that none of the Tracker equipment is lost as this has been the case in the past

I am sure that this is not an exhaustive list and so can be added to and any jobs already done can be removed.