

Using the Crowcon ODH personal monitor

The Crowcon personal Oxygen Depletion Hazard (ODH) monitor is designed to be worn by personnel who need additional ODH protection. These devices are designed to be clipped to the user's belt and will provide an audible alarm and vibrate if the oxygen level drops below a safe level. This level can be adjusted but is set at 19% by default. These monitors are factory calibrated and by default will display the number of months remaining before they require *factory* recalibration.

Prior to use the device will need to perform a self-test which is initiated by briefly pressing the button on the centre right of the unit (see Image 1 below). The unit will beep, vibrate and all the LED elements will light up. After a successful self-test the unit will look like the picture below (Image 2). The unit is now ready to use.

