

QD/QP Commissioning plan Wed 25th to Tues 31st May.

Notes

MICE DC must approve all test procedures.

MICE DC hours 9am to 6pm daily.

Weekend cover same hours 2 out of 3 days over bank holiday weekend only.

1. System check out - Wed afternoon S Feher, A Bross. See MICE_New_QPS_Commissioning_plan-v0.docx section 3 for details.
2. Test QD system triggers QP system.
3. Sign-off interlock approval checklist.
4. Low current PS stability tests. See MICE_New_QPS_Commissioning_plan-v0.docx section 5 for details.
5. High current Tests See MICE_New_QPS_Commissioning_plan-v0.docx section 6 for details.